# Using GIS for Campus and Indoor Facility Operations

2018 ESRI User Conference

July 11, 2018





#### Agenda



- ---- Alamo College Introduction
- ---> Project Overview
- ---> Challenges
- Looking to the Future

# Alamo College Background

- → 58,321 Students
- November 2005 \$450 Million
  Facilities CIP
- → 24 New Buildings
- 1.3 Million Square Feet of Facilities
- → May 2018 \$450 Million Facilities CIP









A L A M O C O L L E G E S

NORTHWEST VISTA COLLEGE



A L A M O C O L L E G E S

PALO ALTO COLLEGE



A L A M O C O L L E G E S

SAN ANTONIO COLLEGE





#### ALAMO COLLEGES SERVICE AREA

Counties: Atascosa, Bandera, Bexar, Comal, Guadalupe, Kendall, Kerr, and Wilson



#### ALAMO COLLEGES SERVICE AREA

Existing and Proposed College Campus Locations





### **Facilities History of Alamo Colleges**

- → Active sensor system
- → Space Utilization Study Performed in 2005
- → Maximo used to Manage Assets since 2008
- → Facility Condition Index (FCI) and Asset Data

Age Range of Buildings	Number of	GSF in Age	% of Total
	Buildings	Range	(GSF)
Greater than 50 Years Old	33	991,893	18%
Between 25 and 50 Years Old	32	1,051,727	19%
Between 10 and 25 Years Old	53	710,988	13%
Less than 10 Years Old	89	2,771,388	50%
Total	207	5,525,996	100%



#### **Previous GIS Efforts**

- → Phase I Project Northeast Lake View Campus (NLC)
- → Test and Implement ESRI Database
- → Convert Existing Data to GIS





### **Previous GIS Efforts**

- → Based on ESRI Data Models
  - Building Interior Space Data Model (BISDM)
  - Local Government Information Model
- → Project Workflow
  - Incorporate Asset Data from Maximo to GIS
  - Georeference AutoCAD As-Built DWGs
- ---> Deliverables
  - Campus GIS





#### **NLC – Campus GIS**





#### **Phase II Project Goals**

- → Identify and develop service maps for NLC
- → Blending GIS & asset management
- → NVC Campus GIS







### **Phase II Challenges**

- → Do more with less
- → Duplicate the creation of a GIS on another campus
  - NLC was new with "average" drawings
  - NVC has some "average" for new buildings
  - NVC lacks detail for original buildings



**Emergency Services Maps:** 

- → Tornado Shelter locations
- → Emergency evacuation maps including building rally points
- → Locations of OSHA confined spaces
- → Fire Protection system





Student Services Maps:

- --- ADA parking
- --- Non ADA parking
- Motorcycle parking
- Bicycle parking
- Disk golf locations
- --- Walking paths
- --- Locations of information monitors





**Emergency Services Maps:** 

- Emergency phones interior and exterior
- ID access control lock doors
- ---> Fire Alarm
- Emergency eye wash and emergency shower locations
- Fire lane locations



Sustainability Maps:

- Soap/paper towel dispensers
- Parking lot and exterior pedestrian lighting
- → Building wall pack lighting
- Interior lighting by room, by floor, by building



#### Sustainability Maps:

- → Floor surface types
- → Recycle bins by size
- HVAC sensors and controls
- Chillers, air handler units, pumps, valves
- → Solar suitability



Facilities Maps:

- --> Sanitary sewer
- --- Storm sewer system
- → Electrical system
- Telecommunications
  systems



#### Facilities Maps:

- Roof access ladders and hatches
- --> Landscaping
- Irrigation system
- Domestic water system
- Natural gas system
- --- Geotech borings



#### **Ongoing Project Results**





# Key Takeaways

- → Utilize Existing Data
- ---> Verify Data
- → Semi Automated with Manual Interaction
- → Build as Effort Allows
- → Wide variety of future uses



#### Questions





#### **Questions?**



John Strybos, PE

Associate Vice Chancellor of Facilities, Alamo Colleges jstrybos@alamo.edu



#### Matt Manges, PE, CFM

Regional Manager, LAN mjmanges@lan-inc.com 832-457-2411

